



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

October 1, 1999

TO: Minerals File

FROM: Doug Jensen, Reclamation Specialist *D. Jensen*

RE: Site Inspection, Rock Products, Develon Wurth Mine, S/043/017, Summit County, Utah

Date of Inspection: September 15, 1999
Time of Inspection: 1030 AM
Conditions: Warm and Clear
Participants: Lynn Kunzler and Doug Jensen DOGM

Purpose of Inspection: Site Assessment and GPS for Total Disturbance

The site was active when the inspection was taking place. A total of five men and a trackhoe were working the main face of the pit. There were no apparent stockpile areas on the site. The site was clean by most standards with no trash accumulations or junk vehicles occupying the area. Photos were taken during the visit.

There were two trailers located on the site, where it was apparent that several of the employees were living.

The GPS unit was used to map the area of disturbance. There were two main areas that had been worked, the one where the men were working and a smaller pit was located above this area. A small prospect pit, located off an switchback, on the site road was also noted. The total disturbed area contained in these two main areas was 4.6 acres. This did not take into account the two access roads and an internal road. The acreage contained in these roads totaled .5 acres. The combined total for the entire site was 5.1 acres.

This survey indicates that the operator will need to address the fact that his operation has eclipsed the five acre threshold. He will need to reclaim, to once again have his site below that 5 acre limit or apply for a Large Mine Permit. The operator will be instructed that he will not be able to expand beyond the areas presently disturbed until this problem has been addressed.

The operator was not on the site at the time of the inspection, therefore a letter will be sent to him informing him of the situation.